FIG. 1 BLOCK CHART

10

- 1. Preparing a hollow metal tube.
- 2. Preparing an outer mold.
- 3. Preparing two inner molds.
- 4. Placing the hollow metal tube in the outer mold and properly positioning the outer mold and the inner mold.
 - 5. Pushing the inner molds at the same time in the metal tube for leveling two needed sections of a string groove of the hollow metal tube.




FIG.1




FIG.2







FIG.3







__




FIG.7




FIG.8